

OGI Inspection -

Mission Name

MISSION DETAILS

ID 145892
Date Dec. 24, 2025
Type OGI Inspection

Meteorological Info	Condition	Fair
	Wind Speed (mph)	9
	Wind Direction	SW
	Ambient Temp (F°)	77



Report Summary

Count of anomalies

Symbol

1





Video	Timestamp	Anomaly	Component/ Sub-Component	Description	Dwell Time	Distance From Component (ft)	Drone Coordinates
-------	-----------	---------	--------------------------	-------------	------------	------------------------------	-------------------

Link to Video	09:01	Emission	Tithe Hatch	Emission detected from tithe hatch	15 Seconds	168	-
-------------------------------	-------	----------	-------------	------------------------------------	------------	-----	---



Video	Timestamp	Anomaly	Component/ Sub-Component	Description	Dwell Time	Distance From Component (ft)	Drone Coordinates
Link to Video	-	None	-	No Emission Found	15 Seconds	-	-



Video	Timestamp	Anomaly	Component/ Sub-Component	Description	Dwell Time	Distance From Component (ft)	Drone Coordinates
Link to Video	-	None	-	No Emission Found	15 Seconds	-	-

Flight Path:

